

FIRST RE-ESTABLISHMENT

GCDB 100100

Township Corner to Townships 32 and 33 South, Ranges 3 and 4 East.

Found no evidence of the corner monument, which location falls in the middle fork of Rogue River and is subject to overflow.

- One of the original BT stumps, plainly scribed, was found washed down stream about 100 feet.
- The other original BTs have been destroyed.
- We did find a Douglas Fir tree with metal tag attached as set by the capable Distance Forest Ranger, Mr. R. M. Beeman, on April 6, 1950. Said tag reads North 130 feet and West 20 feet from the corner. The said tree is now down, but the broken roots which match the tree are still in place in the ground. Established said tagged tree. The record of Mr. Beeman's establishment can be found in the U.S. Forest Service Office. A Photostat of said establishment is also on file in the duplicate corner renewal records in the Jackson County Surveyor's office.

Set a witness corner to wit: a 1"x36" galvanized iron pipe 33" in the ground with a 2½" bronze cap stamped:

"T32-33 S R 3-4 E Township Cor. N. 142 feet. Township Cor. CS-1960"

From said witness corner, I mark the following trees:

- A 20" hemlock scribed "CS-BT" bears South 69° East, 26.3 feet;
- A 6" hemlock scribed "CS-BT" bears North 52¾° East, 49.6 feet;
- A 3" White Fir scribed "CS-BT" bears North 33½° West, 13.7 feet;
- A 4" Douglas Fir scribed "CS-BT" bears South 68½° West, 14.65 feet.

Note: All distances were taken to the face of the scribe.

November 23, 1960
C. Z. Boyden
John Gartman