

FIRST RE-ESTABLISHMENT

GCDB 100440

Quarter corner common to Section 13, Township 32 South, Range 3 East and Section 18, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 6 ins. in a large mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T32S
R3E | R4E
S13 | S18
1962

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1884,

- A sawed Fir stump, brs. S 51°W, 13.9 ft. to center at base. Record; S 45° W.

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center at base:

- D. Fir, now 27 ins. diam. brs. record; S 22° E, 26.4 ft.
- D. Fir, now 18 ins. diam. brs. record; N 85° W, 11.9 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 6 ins. diam. brs. S 2° W, 19.2 ft.
- W. Fir 11 ins. diam. brs. N 78¾° E, 18.3 ft.

Corner lies approx. 200 ft. north of gravel road.

July 28, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 19
V. – 15°50'