

FIRST RE-ESTABLISHMENT

GCDB 200440

Quarter corner common to Sections 17 and 18, Township 32 South, Range 4 East, W.M. $V = 20^\circ$

Found firmly set, the original 18x14x10-inch stone (broken) marked: "¼" on West face, as recorded by R. Moore in 1884.

The only evidence of original bearing trees found was a stump hole at record location of SE BT.

I replaced said stone with, and deposited it alongside, a 1x36-inch Galvanized iron pipe, set 33 inches in the ground, with a 2½-inch bronze disc marked:

JACKSON COUNTY 1978

T32S R4E

18 | 17

¼S

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- White fir, 18-inch diameter bears N43°E, 33.29 feet.
- White fir, 14-inch diameter bears N12°W, 22.70 feet.

Corner lies on N-S (original) blazed line, on North slope about 125 feet South of location marker on 6-inch diameter fir alongside skid road c. E-W and approximately 200 feet West of West edge of clear-cut.

October 23, 1978

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor