

## FIRST RE-ESTABLISHMENT

GCDB 300100

Section corner common to Sections 32 and 33, Township 32 South, Range 4 East and Section 4 and 5, Township 33 South, Range 4 East, W.M.  $V = 22^\circ$

Found firmly in place the 12x10x10-inch stone, set and recorded by R. S. Moore in 1884 with 2 notches on West and 4 notches on East edges.

I replace with a 2½x30-inch G.I. pipe projecting 11 ins. with 2½-inch diameter brass cap marked:

T32S	R4E
S32	S33
S5	S4
T33S	

From which I found the following original reference trees:

- White Fir, dead and down, approximately 32-inch diameter with "BT" and partial "33" scribe visible bears Record:  $S27^\circ W$ , 13.86 feet to estimated face.
- Fir, dead and down, approximately 8-inch diameter with rotted faces bears Record:  $N72^\circ W$ , 5.94 feet to estimated face.

I marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Fir, 7-inch diameter bears  $N53^\circ E$ , 31.5 feet.
- Douglas Fir, 10-inch diameter bears  $S28\frac{1}{4}^\circ E$ , 32.2 feet.
- Hemlock, 9-inch diameter bears  $S66^\circ W$ , 57.5 feet
- Douglas Fir, 14-inch diameter bears  $N54\frac{1}{2}^\circ W$ , 22.2 feet.

I place found stone alongside and raise mound of stone around corner and drove monument marker sign 1½ feet North from corner.

Corner lies approximately 45 feet North of skid road, course: Northwest-Southeast.

November 16, 1979  
J. Gallegos  
H. Center

Approved by: Edward McGinty  
County Surveyor