

FIRST RE-ESTABLISHMENT

GCDB 300140

Quarter corner to Sections 32 and 33, Township 32 South, Range 4 East, W.M.

Found the Northeast BT stump with scribe marks visible on the bark. Also roots corresponding to the Southwest BT. For corner a 1" x 36" galvanized iron pipe with 1½" expander on top filled with pot metal which is stamped:

"32-33 T 32 S R 4 E CS ¼ Corner 1955"

Set 16" in the ground and erected a concrete post 12" x 12" top and 18" high around said pipe:

From which:

- A 7" White Fir scribed CS-BT bears N. 14° E., 19.2 feet;
- A 10" Sugar Pine scribed CS-BT bears S. 89° W., 23.3 feet.

July 20, 1955
C. Z. Boyden
John L. Gartman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 300140

Quarter corner common to Sections 32 and 33, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 12 inches and in concrete, the 1-inch diameter galvanized iron pipe with 2-inch diameter pot metal filled reducer set on First Re-establishment in 1955, marked:

T32S R4E
32 | 33
C.S. ¼ Cor. 1955

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1884,

- A sawed, rotted fir stump 36-inch diameter bears Record: N 65° E, 12.5 feet.

Bearing trees recorded on said First Re-establishment found with healed double blazes and measured to center of trees at lower blaze:

- White Fir, now 21-inch diameter bears N 14° E, 17.7 feet. Record 19.2 feet (slope).
- Sugar Pine, now 31-inch diameter bears S 89° W, 25.9 feet. Record: 23.3 feet.
- Bearing tree of unknown origin and noted on Survey No. 8997, a White Fir 21-inch diameter with a healed single blaze bears N 30½° W, 11.8 feet.

Marked new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- White Fir 11-inch diameter bears N 46° W, 37.1 feet.
- No tree available to south due to road.

Corner lies atop of cut slope approximately 30 feet north of gravel road.

August 16, 2007

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. - 194

V. - 20°30'