

FIRST RE-ESTABLISHMENT

GCDB 400140

Quarter corner common to Sections 33 and 34, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 2 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½" brass cap set by the BLM in 1966, marked:

T32S R4E
¼
S33 | S34
1966

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1884,

- A Hemlock, now 18 ins. diam. with a healed blaze, brs. S 13½° W, 3.3 ft. to center at lower blaze. Record; S 24° W.

Bearing trees recorded by the BLM in 1966, found and measured to center at base:

- Yew, now 11 ins. diam. with scribe marks "¼ S34 BT" in partially healed single blaze, brs. record; S 5° E, 14.5 ft.
- Yew, now 7 ins. diam. with scribe marks "¼ S33 BT" in partially healed single blaze, brs. record; S 32° W, 16.5 ft.

Mark new bearing tree "CS" BT" and take measurement to center of tree at lower blaze:

- Hemlock 16 ins. diam. brs. N 7½° W, 17.6 ft.

Corner lies approx. 150 ft. north of gravel road and approx. 25 ft. south of creek. C. – westerly.

June 21, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 100
V. – 17°50'