

## FIRST RE-ESTABLISHMENT

GCDB 400400

Section corner of Sections 15, 16, 21 and 22, Township 32 South, Range 4 East, W.M.  $V = 20^\circ$

From the following original evidence at the location described below, I set a 1x36-inch Galvanized iron pipe, flush with the surface of the ground, with a 2½-inch bronze disc marked:

Jackson County 1978 T32S R4E	
16	15
21	22

- An original bearing tree recorded by R. Moore, in 1884, a hemlock, now a snag, 19-inch diameter marked: "T32S R4E S22" bears Record:  $S66^\circ E$ , 33.00 feet to scribed face.
- Hemlock stump remains found at record location of original NE & NW bearing trees.
- Original stone not found.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas fir, 24-inch diameter bears  $N28\frac{1}{2}^\circ E$ , 77.1 feet.
- Hemlock, 14-inch diameter bears  $S35\frac{1}{2}^\circ E$ , 35.7 feet.
- Hemlock, 16-inch diameter bears  $S13\frac{1}{2}^\circ W$ , 37.1 feet.
- Hemlock, 13-inch diameter bears  $N28^\circ W$ , 58.3 feet.

Corner lies about 700 feet south of location marker on 30-inch diameter Douglas fir alongside road.

October 13, 1978

B. Malotte

Witness: T. Newcomb, USFS

Approved by: Edward McGinty  
County Surveyor