

FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 2 ONLY
GCDB 540700

North quarter corner to Section 2 only, Township 32 South, Range 4 East, W.M.

Found at the corner position the 1-inch diameter galvanized iron pipe with the 2½-inch diameter brass cap exposed 8 inch set by Price and Carter of the GLO in 1937 and marked:

—————
¼ S2
1937

Single remaining bearing tree recorded by the GLO in 1937 found with healed double blazes and measured to center at lower blaze:

- Fir now 28-inch diameter bears Record: S 37° E, 17.2 feet.

Marked new bearing tree with "CS" and "BT" and measured to center at base:

- S. Red Fir 27-inch diameter bears S 47° W, 30.7 feet.

Corner lies approximately 200 feet east of logging spur.

October 17, 2006

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P. - 183

V - 14°50'