

## FIRST RE-ESTABLISHMENT

GCDB 700400

Section corner common to Sections 13 and 24, Township 32 South, Range 4 East, W.M. on the Jackson-Klamath County line.

Found tipped over, the original 16x10x8-inch stone, marked with 3 notches on opposite sides, by R. Moore in 1884.

Replaced found stone with and deposited it alongside a 1x36-inch Galvanized iron pipe, set 30 inches in the ground with a 2½-inch diameter brass cap marked:

T32S	
R4E	R5E
13	
—	
24	
C.S.	
1986	

- Fir snag, now 15-inch diameter, with scribe marks including "32S R5E S18 visible in exposed upper face bears N52½°E, 16.50 feet to said face. Record: N49°E.
- The rotted remains of a conifer stump, with a weathered face showing scribe marks, including "SR4E S24" found alongside bears Record: S44°W, 19.1 feet to estimated original position of face.
- A broken top Hemlock, now 9-inch diameter with scribe marks visible in partially exposed face bears Record: N54°W, 13.20 feet to scribed face.

Mounded stones around corner, marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Hemlock, 20-inch diameter bears S0°30'W, 69.89 feet.
- Red Fir, 33-inch diameter bears N72°W, 75.95 feet.

Placed a location tag on a 10-inch diameter Red Fir, on the easterly side of road No. 3795, approximately 1,500 feet West of corner. From this tag the East end of a 14-inch diameter corrugated metal pipe bears N78°W, 20.8 feet.

Corner lies in a small opening, approximately 80 feet North of the crest of a 20% northerly slope.

August 21, 1986

D. Edwards

R. Frost

Edward McGinty

County Surveyor

V = 18°

P. -223