

**RE-ESTABLISHMENT (by Douglas County)**  
**QUARTER CORNER TO SECTION 33 ONLY**  
**GCDB 340100**

Standard ¼ Corner common to Section 33, Township 32 South, Range 4 West, W.M.

Found:

- 12-inch Cedar (rec. Fir), now 20-inch S50°W, 16.5 feet, opened for scribe (ring count places age approximately 1885).
- 6-inch Fir, down-rotten, N45°W, 4.0 feet, has very old rotten face, maybe very faint scribe.

Set brass cap at corner marked:

County Surveyor's Office	
1970	
T32S	Doug. Co.
R4W	S 33
—	
T33S	S¼ C
Jack. Co.	

New BTs:

- Douglas Fir N52°E, 15.6 feet marked: "S¼ C S33 CS BT".
- 12-inch Douglas Fir N38°W, 12.7 feet marked: "S¼ C S33 CS BT".
- By pacing, corner hits approximately 9 chains West of CC S33/S34 and 3 chains East of ridge.

May 14, 1970

W. Penley & J. Heritage (Douglas County)