

## FIRST RE-ESTABLISHMENT

GCDB 260260

Northeast 1/16 corner to Section 29, Township 34 South, Range 1 West, W.M.

Set a 1 x 24 ins. steel gun barrel for corner, from which:

- A 20 ins. Black Oak scribed 1/16 BT which bears  $S61\frac{1}{4}^{\circ}W$ , 127.7 feet.
- Scribed a 16 ins. White Oak 1/16 BT which bears  $S78\frac{1}{2}^{\circ}E$ , 193.5 feet.

August 9, 1944

C. Z. Boyden

B. L. Campbell

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 260260

NE 1/16 corner located in Section 29, Township 34 South, Range 1 West, W.M.

Found 1 ins. deep the 1 x 24 ins. octagon gun barrel set in 1944 on page 1.

Replaced gun barrel with a 1 x 36-inch Galvanized iron pipe, 38 inches in the ground, with a yellow plastic cap marked: "Jackson CS".

Bearing trees marked in 1944 found with healed blazes and measured to the center of tree at lower blaze:

- Black Oak, 29-inch diameter, bears record S61¼°W, 127.70 feet to estimated face. Re-measured 128.20 feet.
- White Oak, 20-inch diameter, bears record S78½°E, 193.50 feet to estimated face. Re-measured 194.15 feet.

Corner lies on South side of dirt driveway, 8 feet South from center, to residence at 4895 Rogue River Drive. SE bearing tree is about 50 feet East from center of Rogue River Drive.

January 25, 1991  
T. Newcomb, Tech.  
H. Durkee, Tech.

Verlyn Thomas  
County Surveyor

V = 17½°

P.-6