

FIRST RE-ESTABLISHMENT

GCDB 340700

North quarter corner to Section 4, Township 34 South, Range 1 West.

Found

- Stump of original BT to South, the scribe marks legible.
- Also original BT N30°W., 110.88 feet, which check for course but does not check distance, reverse the distances and it will check the course which also checks course and distance run from the section corner.

Set 4x4x36 post for corner from which scribed a 12" red fir C.S. BT which bears S.45°15'E., 63.5 feet.

February 7, 1928
Boyden, Deputy County Surveyor
B. Seaman, Chainman
Bob Kent, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 340700

Quarter corner common to Section 33, Township 33 South, Range 1 West and Section 4, Township 34 South, Range 1 West, W.M.

Found a ½" iron pipe in a mound of stone for corner. Set a 1"x 36" galvanized iron pipe, 32" in the ground with a 2½" bronze cap over said ½" pipe corner monument. Cap stamped:

T33 & 34S
R1W
33
¼S — Cor.
4
C.S.
1972

From which:

- The original Northwest bearing tree, now an 18" White Oak with partially open and rotted faces bears N 30° W, 111.5 feet to the center (original Record: 15" White Oak, N30°W, 29.7 feet)
- First Re-establishment; 15" White Oak N30°W, 110.88 feet.
- The First Re-establishment by Deputy County Surveyor C. Z. Boyden on February 7, 1928 establishes the fact that the distances to the bearing trees in the original notes are reversed.
- The original bearing tree to the South, now a 7 foot high broken off Pine stump with "S BT" scribe visible bears S½°E, 29.1 feet to the face of the lower blaze (original Record: 18" Yellow Pine South, 110.88 feet).
- The stump hole of the bearing tree established on the said First Re-establishment checks the record.

Scribe a 10" White Oak "CS-BT" which bears N42½°E, 10.5 feet to the face of the lower blaze.

Scribe a 7" White Oak "CS-BT" which bears S71¼°E, 10.25 feet to the face of the lower blaze.

March 28, 1972
G. Kaiser, Deputy County Surveyor
L. Woodcock