

FIRST RE-ESTABLISHMENT

GCDB 440500

Quarter corner between Sections 10 & 15, Township 34 South, Range 1 West.
Found original BT to the Southeast no evidence of BT to Northwest.

Set a 1"x 36" galvanized iron pipe 30" in the ground for corner.

From which:

- Original bearing tree a 30" Black Oak bears South 1° East, 105.6 feet
- Scribed an 8" Black Oak CS-BT which bears North 19°30'West, 113.1 feet.

Var. 21°30'East
July 15, 1936
C. Z. Boyden,
Deputy County Surveyor

D. Clifford
F. Young

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440500

Quarter corner to Sections 10 and 15, Township 34 South, Range 1 West.

Found the 1" pipe corner monument and a 10" Black Oak plainly scribed "CS" which bears North 19°30' West, 113.1 feet which were set by C. Z. Boyden in the First Re-establishment in 1936;

Also found the stump of the original bearing tree to the Southeast.

From said pipe corner, I take a new witness tree as follows:

- A 16" Black Oak, scribed "CS-BT," bears South 52½° West, 110.0 feet.

August 8, 1955

M. E. Boyden

L. D. Berntson

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 440500

One Quarter corner common to Sections 10 and 15, Township 34 South, Range 1 West, W.M.

It being impractical to set a monument at the corner point which falls about the Southeast edge of a 2¼ ins. by 5 feet high metal fencepost, set in concrete, the corner of North-South & Easterly fence lines:

I set a witness corner; a 1x36-inch G.I. pipe, 30 ins. in the ground with a yellow plastic insert marked:

JACKSON

COUNTY

From which:

- I take measurements to bearing trees noted on Second Re-establishment (page 11) in 1955.
- Black oak, 20-inch diameter, with healed blazes, bears S50°W to center of tree at lower blaze, 110.00 feet to nail in Southeast side of tree.
- Black oak, 13-inch diameter, with healed blazes, bears N18°20'W, to center of tree at lower blaze, 108.00 feet to nail in East side of tree.
- The center of the top of a found black iron pipe, 1-inch diameter , bears S33°45'E, 5.94 feet
- A found 5/8 ins. smooth iron pin (Basis of brs: reference survey no. 3404 dated 1967,) bears S37°25'51"E, 308.15 feet.
- The ¼ corner point (no monument) bears S37°25'51"E, 6.00 feet

See also Jackson County Project File No. 79-3.

January 16, 1979
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR ADDENDUM TO THIRD RE-ESTABLISHMENT

**ADDENDUM TO THIRD RE-ESTABLISHMENT
GCDB 440500**

Found yellow plastic cap marked "R. Roberts LS 1656" on $\frac{5}{8}$ " rebar 6 ins. deep, set on Survey No. 7991, dated September 12, 1979, to mark the position of the reference monument (witness corner) set January 16, 1979, which had been removed.

April 15, 2003
H. Durkee
T. Newcomb

Roger R. Roberts
Jackson County Surveyor