

## FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter corner to Sections 22 and 23, Township 34 South, Range 1 West, W.M.

Found post set for corner; also original BTs to Northwest and Southeast, both dead, with scribe marks visible; from which evidence:

Set a 1"x 36" galvanized pipe 28" in the ground for corner alongside of the old post as described in the official records; from which corner:

- A 12" White Oak scribed C.S.-BT bears S.62½°W. 24.7 feet.
- Scribe an 8" White Oak C.S.-BT which bears N.52¼°E., 57.9 feet.

June 5, 1935  
C. Z. Boyden,  
Deputy County Surveyor

O. H. Tice, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23, Township 34 South, Range 1 West, W.M.

Found 5 ins. deep, near middle of (gravel) road, the ¾-inch diameter rebar, set on Survey No. 5578, dated 1974. Atop found rebar, set a 2½-inch diameter bronze cap marked:

JACKSON COUNTY  
T34S R1W  
¼ S  
22 | 23  
C.S.  
1987

- An original bearing tree marked by Ives and Hyde in 1854, now a pine stob, 12-inch diameter, scribed "¼" & "BT" in exposed faces, bears Record: S38°E, 36.3 feet to (original) axed chain notch.

Bearing trees marked on First Re-establishment, found as follows:

- White Oak, 10-inch diameter, with healed blazes, bears N54°10'E, 57.9 feet to estimated face. Re-measured 58.23 feet to center of tree at lower blaze. Record: N52¼°E.
- White Oak, 16-inch diameter, with partly exposed lower face, bears S62°30'W, 24.2 feet to lower face, 24.8 feet to center of tree at lower blaze. Record: 24.7 feet.

Take new references:

- The center, base, of a 2½-inch diameter, 7-foot high steel gate post set in concrete, bears S39°54'E 18.04 feet.
- A 5/8 x 24-inch rebar, with yellow plastic cap marked "Jackson C.S.", located 3 feet West of 6-inch diameter white oak, with old fence wire attached, bears N85°06'E, 17.55 feet.

Corner lies about the end of curve in road, the forward tangent of which bears South. See also Jackson County field notes page 316.

August 27, 1987  
R. Frost, Tech  
S. Beecher, Tech

Edward McGinty  
County Surveyor

P.-316

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23, Township 34 South, Range 1 West, W.M.

Found at the corner position and 9 ins. deep the 2½-inch diameter brass cap set atop a found ¾ inch diameter rebar on Second Re-establishment in 1987, marked:

JACKSON COUNTY  
T34S R1W  
¼ S  
22 • 23  
C.S.  
1987

Snugged said brass cap back down on rebar as it was loose and askew, and poured 6 inches deep concrete collar flush with brass cap.

Bearing trees recorded on First Re-establishment in 1935, found with healed double blazes and measured to center of trees at lower blaze:

- White Oak, now 16-inch diameter bears Record: S62°30'W, 24.8 feet.
- White Oak, now 11-inch diameter and leaning easterly bears Record: N54°10'E, 58.2 feet to center at base.

Take new reference, 5/8 x 24 ins. rebars with 1½-inch diameter bronze caps, set flush br.:

- N77°43'20"W, 14.79 feet. Set 1 foot east of 6-inch diameter x 10-foot high fence corner post. Fence bears northerly and westerly.
- S04°52'27"W, 15.07 feet set at westerly edge of road and 6 ins. east of 3½-inch diameter x 7-foot high steel post.

Corner lies on westerly edge of graveled road approximately 500 feet southerly of intersection with Indian Creek Road.

June 7, 2005

H. Durkee

B. Smith - witness

Roger R. Roberts

Jackson County Surveyor

P. - 75