

FIRST RE-ESTABLISHMENT

GCDB 600500

Corner common to Sections 11, 12, 13 and 14, Township 34 South, Range 1 West, W.M.

Set a 1"x 36" galvanized iron pipe 30" in the ground in a mound of rock with a 2½" bronze cap stamped:

T34S R1W
11 | 12
Sec. —+— Cor.
14 | 13
C.S.
1970

For corner.

From which:

- The original bearing tree (now a 13" Black Oak, with rotted faces) bears N 56¾° W, 53.1 feet to center of the tree;
- The original bearing tree (now a dead and down Yellow Pine with scribe marks visible) bears N 16¾° E, 21 feet to the center of the stump hole;
- The original bearing tree (now a dead and down Black Oak, with scribe marks visible) bears S37¾°W, 33.7 feet to the center of the stump hole.

Marked new trees as follows:

- A 6" Cedar scribed "CS-BT" bears N1°E, 23.4 feet. to the face of the lower blaze;
- A 14" Yellow Pine scribed "CS-BT" bears S7¼°E, 41.9 feet to the face of the lower blaze;
- A 7" Yellow Pine, scribed "CS-BT" bears S80¾°W, 37.0 feet to the face of the lower blaze;
- A 12" Laurel (northerly tree in stool) scribed "CS-BT" bears N69¼°W, 52.8 feet to the face of the lower blaze.

December 17, 1970
O. Blankenship
J. Gartman

Approved By:
Mark E. Boyden
County Surveyor