

FIRST RE-ESTABLISHMENT

GCDB 140200

Quarter Section Corner 30 - 31, Township 34 South, Range 2 East.

Found the original cedar BT to Northwest with the $\frac{1}{4}$ S and B scribe legible.

From which:

- Set a 1"x 36" galvanized iron pipe 33" in the ground for corner from which the original B T, now a 42" cedar, the original BT bears North 88° West 6.6 feet.
- Also put a new BT scribe on the said BT.
- Scribe an 8" Douglas fir CS-BT which bears North $76\frac{1}{2}^{\circ}$ East 15.1 feet.

November 5, 1954
C. Z. Boyden
H. T. Furnas
M. E. Boyden