

## FIRST RE-ESTABLISHMENT

GCDB 200700

Section corner on the Township line to Sections 31 and 32, Township 33 South, Range 2 East, and Sections 5 and 6, Township 34 South, Range 2 East.

Found the original corner stone with 5 notches on the East and 1 notch on the West edges (stone badly broken). Also found stump holes corresponding to the original BTs.

Replaced the old stone with a new basalt stone 6" x 8" x 12" with 1 notch on the West face and 5 notches on the East face, together with an X on top set in a mound of stone for corner.

From which a 9" Cedar scribed CS-BT bears N23°E, 13.2 feet;

- Scribe a 10" Douglas Fir CS-BT which bears N69°W, 41.2 feet.
- Scribe a 28" Cedar CS-BT which bears S36°W, 30.0 feet.
- Scribe a 5" Dogwood CS-BT which bears S25½°E, 32.0 feet.

August 25, 1955  
C. Z. Boyden  
E. W. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 200700

Section corner common to Sections 5 and 6, Township 34 South, Range 2 East and Sections 31 and 32, Township 33 South, Range 2 East, W.M.

Found, firmly set and projecting 5 ins. from a small mound of stones, the 12x8x6 ins. stone with cross on top, 5 notches on East face and 1 notch on West face, as reported on First Re-establishment, page 5, in 1955.

Replace said stone with and deposit alongside of, a 1x36-inch Galvanized iron pipe set 28 ins. in the ground. In the top of said pipe, set in concrete, a 2½-inch diameter brass cap marked:

T33S	R2E
31	32
6	5
T34S	
C.S.	
1987	

All original bearing trees gone.

Bearing trees marked on said First Re-establishment found and measured to center of trees at base:

- Cedar, now 13-inch diameter with scribe marks visible on partially healed upper blaze, bears N21½°E, 13.4 feet. Record: N23°E, 13.2 feet.
- Cedar, now 39-inch diameter with double healed blazes, bears S37½°W, 31.2 feet. Record: S36°W, 32.0 feet.

Scribe new trees "CS" "BT" and measure to center of trees at lower blaze:

- Douglas Fir, 10-inch diameter, bears S22°E, 47.0 feet.
- Hemlock, 11-inch diameter, bears N46¾°W, 25.5 feet.

Corner lies in timber on an 18% northeasterly slope.

May 6, 1987  
D. Edwards - Tech II  
T. Newcomb - Tech I

Edward McGinty  
County Surveyor

V = 18½°

P. -137