

FIRST RE-ESTABLISHMENT

GCDB 240400

Quarter corner common to Sections 17 and 20, Township 34 South, Range 2 East, W.M.

Found original pine BT fallen down with scribe visible. Cadastral Engineers notes call for N65°E, 226 lks. Believing the course should have been N65°W, I obtained Mr. A. E. Abbot who has seen the BT and corner many times. Mr. Abbot identified the facing of the scribe also the approximate location of the corner which shows the course should have read N65°W, 226 lks.

Set 1"x 36" galvanized pipe 18" in the ground in mound of stone for corner from which

- The original BT bears N65°W, 149.16 feet.
- A 24" White Oak scribed CS-BT bears S51°10'E, 450.2 feet
- A 36" yellow pine scribed C.S.-BT bears N6°15'E, 528.0 feet.

February 5, 1931
C. Z. Boyden,
Deputy County Surveyor

L. Pettegrew, Chainman
A. E. Abbott, Chainman
O. H. Tice, Chainman