

FIRST RE-ESTABLISHMENT

GCDB 300540

Quarter corner common to Sections 8 and 9 of Township 34 South, Range 2 East, W.M.

Found at corner position, exp. 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968 and marked:

T34SR2E
¼
S8 | S9
1968

Single remaining original bearing tree recorded by Nathaniel Ford of the G.L.O. in 1885 found and measured to center at base;

- Fir stump rotted remains brs. record N45°E, 15.5 ft.

Bearing trees recorded by the B.L.M. in 1968 found with a healed single blazes and measured to center at base,

- W. fir now 25 ins. diam. brs. record S41°E, 132.7 ft.
- W. fir now 15 ins. diam. brs. N76°W, 28.6 ft. ; record 28.4 ft..

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 11 ins. diam. brs. S76°W, 28.6 ft.
- D. fir 7 ins. diam. brs. N42½°E, 21.6 ft

Corner lies approx. 150 ft. south of gravel road.

April 15, 2009

B. Beeman

H. Durkee

Kerry Bradshaw

Jackson County Surveyor

P. – 82

V. – 17°05'