

FIRST RE-ESTABLISHMENT

GCDB 340700

Quarter corner common to Section 33, Township 33 South, Range 2 East and Section 4, Township 34 South, Range 2 East, W.M.

Found original B.O. in Section 33 down and fir in Section 4 intact.

Set corner and new bearing tree a 12" fir which bears N66°E, 17.01 feet.

June 20, 1917
A. T. Brown,
County Surveyor

T. E. Sandoz, Chainman