

## FIRST RE-ESTABLISHMENT

GCDB 400400

Section corner common to Sections 15, 16 and 21 only of Township 34 South, Range 2 East, W.M.

Found at corner position , exposed 10 ins., in a large mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1974 and marked:

T34SR2E  
S16 |  
----- | S15  
S21 |  
1974

Original bearing trees recorded by Eugene Henry of the GLO in 1908 found with healed blazes and measured to center at base;

- Madrone now 19 ins. diam. with opened blaze brs. record; S50°E, 37.0 ft.
- W. oak snag with partially healed blaze scribed 'S21''BT' brs. S51°W, 13.2 ft. record ; S50°W
- Plum dead, down, and rotted brs record ; N46½°W, 56.1 ft. to center of stump hole

Bearing trees recorded by Smeltzer per BLM records, found with healed double blazes and measures to center at lower blaze;

- Fir snag brs. S59°E, 20.5 ft. record ; S60°E
- Fir 11 ins. diam. and dying brs. record S79°W, 19.1 ft.

Bearing trees recorded by the BLM in 1974 found with healed single blazes and measures to center at base;

- D. fir now 26 ins. diam. brs. record; N78°W, 55.8 ft.
- D. fir now 29 ins. diam. brs. record; S64½°W, 10.6 ft.

Marked new bearing tree "CS" "BT" and measured to center at lower blaze:

- D. fir 9 ins. diam. brs. N48¾°E, 11.4 ft.

Corner lies approx. 550 ft. north of bend in gravel road.

April 19, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 90

V. – 15°20'