


FIRST RE-ESTABLISHMENT

GCDB 400500

Closing corner common to Sections 10, 15 and 16, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones with an aluminum post and sign 1 ft. north, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1974, marked:



Original bearing trees recorded by Eugene Henry of the GLO in 1908, found with healed blazes and measure to center at base:

- Rotted fir high-stump 32 ins. diam. brs. N32½°E, 20.0 ft. Record; 20.5 ft.
- Sawed fir stump 30 ins. diam. brs. record; S7½°E, 44.2 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. fir 9 ins. diam. brs. S31°E, 11.7 ft.
- Madrone 9 ins. diam. brs. N72¾°E, 12.6 ft.

Corner lies approx. 70 ft. west of gravel road.

April 21, 2010

H. Durkee

B. Beeman

Kerry K. Bradshaw

Jackson County Surveyor

P. – 92

V. – 14°05'