

GCDB 440600

Quarter corner common to Sections 3 and 10, Township 34 South, Range 2 East, W.M.

SEE RECORDED SURVEY NO. 2954

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

FIRST RE-ESTABLISHMENT

GCDB 440600

Quarter corner common to Sections 3 and 10 of Township 34 South, Range 2 East, W.M.

Found at corner position exposed 2 ins. in mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968 and marked:

T34S R2E
S3
¼ ———
S10
1968

Single remaining original bearing tree recorded by Nathaniel Ford of the GLO in 1855 found,

- A Hemlock dead, down and rotted brs. record S27°W, 4.6 ft., to center of stump hole.

Bearing tree recorded on Survey #2954 in 1965 found with exposed single blaze with scribe 'S 10 BT' and measured to center at base:

- Hemlock rotted stob brs. record N37°W, 33.7 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 11 ins. diam. brs. N17½°W, 13.5 ft.
- W. fir 6 ins. diam. brs. N21°E, 11.5 ft.
- D. fir 10 ins. diam. brs. S38½°W, 22.1 ft.
- Madrone 5 ins. diam. brs. S16½°E, 6.2 ft.

Corner lies approx. 75 ft south of logging road

April 14, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 80

V. – 17°45'