

**GCDB 500340**

Quarter corner common to Sections 22 and 23, Township 34 South, Range 2 East, W.M.

**SEE RECORDED SURVEY NO. 2954**

**SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT**

## FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23 of Township 34 South, Range 2 East, W.M.

Found at corner position exposed 9 ins. in a mound of stones and steel fence post 1 ft. south, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968 and marked:

T34S R2E  
¼  
S22 | S23  
1968

Single remaining original bearing tree recorded by Eugene B. Henry of the GLO in 1908 found,

- A fir snag now blown down and measured to center of stump hole brs. record; S54°W, 11.9 ft.

Bearing trees recorded by the BLM in 1968 found:

- Fir now blown down brs. record; S88°E, 69.3 ft. to center of stump hole.
- W. fir now snapped off with healed single blaze brs. record; N10°W, 20.5 ft. to center at base.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 10 ins. diam. brs. N19½°W, 28.8 ft.
- D. fir 10 ins. diam. brs. N81¼°W, 9.5 ft.
- W. fir 6 ins. diam. brs. N70¾°E, 15.5 ft.
- D. fir 15 ins. diam. brs. S7¾°W, 35.4 ft.

Corner lies approx. 500 ft. east of logging spur road near top of ridge.

June 17, 2009

H. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P – 117

V – 19°25'