

GCDB 500600

Section corner common to Sections 2, 3, 10 and 11, Township 34 South, Range 2 East, W.M.

SEE RECORDED SURVEY NO. 2954

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

FIRST RE-ESTABLISHMENT

GCDB 500600

Section corner common to Sections 2, 3, 10 and 11, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. Iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968, marked:

T34S R2E
S3 | S2
—+—
S10 | S11
1968

Single remaining original bearing tree recorded by N. Ford of the GLO in 1855:

- A sawed fir stump brs. S63°E, 53.5 ft. to center. Record; S59°E.

Bearing trees recorded on Survey No. 2954 in 1965, found with healed single blazes and measured to center at base:

- W. fir, now 11 ins. diam. brs. N29°E, 8.3 ft. Record; N33°E.
- Fir, dead and down brs. N77°W, 12.9 ft. to center of stump remains. Record; 12.5 ft.

Bearing tree recorded by the BLM in 1968:

- A D. fir now 24 ins. diam. with a healed single blaze brs. S78°W, 37.3 ft. to center at base. Record; 37.0 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. fir 13 ins. diam. brs. N60¾°W, 25.2 ft.
- W. fir 16 ins. diam. brs. S78½°E, 36.0 ft.

Corner lies approx. 50 ft. south of logging road.

April 14, 2009
H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. - 81
V. - 15°30'