

FIRST RE-ESTABLISHMENT

GCDB 600340

Quarter corner common to Section 23 and 24, Twp. 34 South, Range 2 East, W.M. $V = 17^\circ$

Found, as recorded by E. B. Henry in 1908, the 14x12x8 inches high (in place) stone, marked with cross and "¼" on West face.

I set a 1x36-inch G.I. pipe 14 inches in the ground with a 2½ inches bronze disc, set directly over cross on original stone (pipe leans S.E.) and marked:

Jackson County 1976
T34S R2E
¼S
23 | 24

An original BT, now a burned Fir stump, about 24-inch diameter, bears record $N20\frac{1}{2}^\circ E$, 125.40 feet on slope, to center.

- The location of the original N.W. BT is now in a skid road.

I mound stones around corner, marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 15-inch diameter, bears $N21\frac{1}{4}^\circ E$, 29.29 feet.
- White Fir, 8-inch diameter, bears $N29\frac{1}{4}^\circ W$, 42.48 feet.
- A found post in mound of stone (BLM) bears $S88\frac{1}{2}^\circ W$ 21.3 feet.

Corner lies $S84^\circ E$, 48 feet from location marker, on 6-inch diameter Fir, on East edge of skid road.

February 9, 1976

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor