

**FIRST RE-ESTABLISHMENT  
QUARTER CORNER TO SECTION 24 ONLY  
GCDB 700340**

Quarter corner common to Section 24 only of Township 34 South, Range 2 East, W.M.

Found at corner position, exposed 6 ins., in a mound of stones, at the westerly base of a 30 ins. diam. D. fir, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set the BLM in 1970 and marked:

T34SR2E  
¼  
S24|  
1970

Bearing trees recorded by the BLM in 1970 found with healed single blazes and measures to center at base;

- W. fir dead, down, and rotted brs. record S74°W, 18.2 ft. to center of stump hole.
- D. fir now 17 ins. diam. brs. record N25°W, 22.4 ft.

Marked new bearing tree "CS" "BT" and measured to center at lower blaze:

- W. fir 13 ins. diam. brs. S28½°W, 21.5 ft

Corner lies approx. 300 ft. south of gravel road.

January 11, 2010  
B. Beeman  
H. Durkee

Kerry K. Bradshaw  
Jackson County Surveyor

P. – 8  
V. – 11°35'