

## FIRST RE-ESTABLISHMENT

### GCDB 100240

Quarter corner common to Section 30, Township 35 South, Range 2 West and Section 25, Township 35 South, Range 3 West, W.M.

Found 5 ins. deep, the  $\frac{5}{8}$  ins. diam. iron pin, set on Survey No. 3099, dated 1966, with a  $\frac{3}{4}$  ins. diam. iron pipe found buried along westerly side. Directly over found pin, set a 1x36 ins. galvanized iron pipe, flush, with  $2\frac{1}{2}$  ins. diam. brass cap marked:

T35S  
R3W R2W  
25 | 30  
C.S.  
1987

- A reference tree recorded on the above noted survey, a double blazed white oak, now 16 ins. diam., found with healed blazes. Marked this tree "CS" "BT" and measured to center of tree at lower blaze;  $S89^{\circ}45'E$ , 53.80 feet.
- The original Southwest bearing tree, reported on subject survey is now gone.
- **Note:** The stone reported on road survey; Book 44, page 39 dated 1928 could not be found.

Take new references:

- Chiseled cross, atop the South end of concrete culvert, under approach to private drive of residence No. 8675, brs.  $S47^{\circ}47'W$ , 42.85 feet.
- Found boat spike, 2 ins. deep, near middle of road, brs.  $S87^{\circ}31'W$ , 11.59 feet.
- A found  $1\frac{1}{2}$  ins. diam. galvanized iron pipe, projecting 6 ins., brs.  $S89^{\circ}57'W$ , 41.43 feet.
- The (brass cap) corner of Sections 19, 24, 25 and 30, brs.  $N0^{\circ}10'10"E$ , 2645.27 feet.

Corner lies  $S88^{\circ}42'W$ , 18.3 feet from the (wood) gate and Southwest fence corner post of cemetery and 1 feet East of the East edge of asphalt surface of Ramsey Road.

March 23, 1987  
R. Frost  
E. McGinty

Edward McGinty  
County Surveyor

P.-85