

FIRST RE-ESTABLISHMENT

GCDB 100440

Quarter corner common to Section 13, Township 35 South, Range 3 West and Section 18, Township 35 South, Range 2 West, W.M.

At the corner, set galvanized iron pipe 1 ins. diam., 36 ins. long, 34 ins. in the ground, with 2½ ins. diam. bronze cap marked:

JACKSON COUNTY 1980
T35S
R3W R2W
13 | 18
¼S

From which:

- The stump depression of original NW bearing tree, containing pine roots and fragments, bears Record: N81°W, 51.48 feet
- Original SE bearing tree is now gone.
- The Black Oak stump remains of original line tree recorded by Ives and Hyde in 1854, brs. S0°05'E, 229.7 feet. Record South, 229.68 feet.

Mound stones around corner, mk. new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Cedar, 14 ins. diam., brs. S19°15'E, 40.00 feet
- Cedar, 15 ins. diam., brs. S85°15'E, 34.00 feet.

Note: Old (down) fence line brs. Northerly from corner; blazed line (circa 1945) bears southerly.

Corner lies about 33 feet South of foot of hill and approximately 500 feet North of location marker on 6 ins. diam. Laurel alongside road.

December 9, 1980

R. Frost

R. Templin

Edward McGinty

County Surveyor

V = 19°

P.-228