

## FIRST RE-ESTABLISHMENT

GCDB 440700

Quarter corner on Township line - Section 34, Township 34 South, Range 2 West and Section 3, Township 35 South, Range 2 West.

Found 26" black oak with old axe marks, remains of oak stump to southeast, also sharpened stake below the surface of the ground to mark the corner;

From which evidence set a 1" x 36" galvanized iron pipe 36" in the ground for corner,

From which:

- A 14" black oak scribed C.S.-BT bears N.49°E. 26.9 feet.
- Scribed a 10" white oak C.S.-BT which bears S.57°W. 77.2 feet.

November 1, 1944

C. Z. Boyden

R. E. Welch

B. L. Campbell

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 440700

One-Quarter corner common to Sections 3, Township 35 South, Range 2 West, and Section 34, Township 34 South, Range 2 West, W.M.  $V = 18\frac{1}{2}^\circ$

Found: The 1x36 ins. G.I. pipe set on first re-establishment, page 13, in 1944.

I replace the above with and deposit it alongside a 1 x 36 ins. G.I. pipe, set 2 ins. below the surface of the ground with a 2½ ins. bronze disc marked:

JACKSON COUNTY 1979  
T34S R2W  
34  
¼S —  
3  
T35S

Evidence of original bearing trees recorded by Ives and Hyde in 1854 found as follows:

- Stump remains of down and rotted black oak, bears Record: N21°W, 31.68 feet.
- Stump hole found at record location of original Southeast Bearing Tree.

Reference trees recorded on First Re-establishment:

- Black Oak, now a snag, 15-inch diameter with healed blazes bears Record: N49°E, 26.9 feet to estimated lower face.
- White Oak, 10-inch diameter, with healed blazes, bears S57°W, 77.15 feet to center of tree. Record: S57°W, 77.2 feet.

I mark a new tree "CS BT":

- Black Oak, 12-inch diameter bears N68°E, 39.23 feet.

Corner lies about 330 feet S50°W, from location marker on 12-inch diameter White Oak alongside Antioch road and about 9 feet North of old (down) East-West fence line.

June 5, 1979

J. Swanson

R. Frost


Approved by: Edward McGinty  
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT  
GCDB 440700**

Quarter corner common to Section 34, Township 34 South, and Section 3, Township 35 South, Range 2 West, W.M.

Found at the corner position, exposed 1 in., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap, set on 2<sup>nd</sup> Re-establishment in 1979, marked:



Bearing tree recorded on 1<sup>st</sup> Re-establishment in 1944,

- A w. oak dead and down brs. record; S57°W, 77.2 ft. to center of root hole.

Bearing tree recorded on said 2<sup>nd</sup> Re-establishment,

- A b. oak now 13 ins. diam. with healed double blazes brs. record; N68°E, 39.2 feet to center of trees at lower blaze.

Mark new bearing trees "CS""BT" and take measurements to center of trees at lower blaze:

- W. oak 9 ins. diam. brs. N81½°W, 35.1 ft.
- W. oak 9 ins. diam. brs. S6½°W, 33.6 ft.

Corner lies approx. 400 ft. west of Antioch Road and approx. 6 ft. north of east-west down fenceline.

January 27, 2009

H. Durkee

B. Beeman

Kerry K. Bradshaw

Jackson County Surveyor

P. – 22

V. – 16°10'