

FIRST RE-ESTABLISHMENT

GCDB 500100

Section Corner on Township Line - Sections 34 and 35, Township 35 South, Range 2 West and Sections 2 and 3, Township 36 South, Range 2 West.

Found mound of stone at corner; also original BTs to Northwest and Southeast intact; BT to Southwest dead with scribe legible.

Mound of stone replaced with a 6" x 6" x ? Concrete monument and a 3½" bronze disk marked boundary monument for corner,

From which:

- The face of the BT, a 24" Black Oak bears N.61¾°W, 184.8 feet.
- Scribed a 26" White Oak C.S.-BT which bears S.38½°W, 124.6 feet.
- Scribed a 6" White Oak C.S.-BT which bears N.81¾°E, 41.25 feet.
- The face of the original BT, a 24" Black Oak, bears S.32¾°E. 128.0 feet.

May 14, 1942
C. Z. Boyden
W. R. Young
L. Withers

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 500100

Section common to Sections 34 and 35, Township 35 South, Range 2 West, and Sections 2 and 3, Township 36 South, Range 2 West, W.M. $V = 21\frac{1}{2}^\circ$

Found, 6x6 ins. concrete monument, projecting 5 ins. with $3\frac{1}{2}$ ins. brass cap. I added marks to said brass cap and it now reads:

U.S. ENGINEERS DEPARTMENT
T35S R2W
34 | 35
—+—
3 | 2
1979
Boundary Monument

Bearing trees recorded on first re-establishment (page 18) in 1942 found as follows:

- An original bearing tree, now a sawed White Oak stump, 24 ins. diam., brs. as noted in 1942; $S32\frac{3}{4}^\circ E$, 128.0 feet.
- An original bearing tree now a sawed White Oak stump, scribed "BT" brs. $S38\frac{3}{4}^\circ W$. Distance not measured. Record (1942); $S38\frac{1}{2}^\circ W$, 124.6 feet.

Reference trees marked on first re-establishment are now gone. A stump hole found at record location of Northeast bearing tree.

I mk. new trees CS BT and take measurements to center of trees at lower blaze:

- White Oak, 6 ins. diam., brs. $N83^\circ 17' E$, 43.88 feet.
- White Oak, 7 ins. diam., brs. $S17^\circ 52' E$, 36.00 feet.
- Black Oak, 10 ins. diam., brs. $S74^\circ 38' W$, 76.05 feet.
- Black Oak, 9 ins. diam., brs. $N82^\circ 56' W$, 68.50 feet.

Corner lies on East-West fence line 87 feet West of the post corner of South and West bearing fence lines.

July 30, 1979
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor