

FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter section corner common to Sections 22 and 23, Township 35 South, Range 2 West.

Found a ½" iron pipe for corner and the original southwest bearing tree with a portion of the "B" scribe.

For corner, set a 1" x 36" galvanized iron pipe directly over the ½" pipe with a 2½" bronze cap flush with the ground and stamped:

T35S R2W
¼ 22 | 23 cor
C.S.
1967

From which:

- The original white oak bearing tree, now 36" in diameter, bears South 46° West, 79.9 feet;
- A 10" white oak with two blazes not scribed, bears North 62½° East, 16.0 feet;
- Scribed a 12" black oak CS-BT which bears South 16½° East, 10.4 feet;
- Found a ½" pipe with a tag marked "R.E. 838" which bears South 57° West, 1.74 feet.

Note: In April 1960 L. D. Pinkham and crew report finding the same two half-inch pipes and additional scribing in the original bearing tree.

January 4, 1967
Gary Kaiser
Gerald Nygren

Approved By:
L. D. Pinkham
Deputy County Surveyor