

## FIRST RE-ESTABLISHMENT

### GCDB 600100

Re-establishment section corner on township line Sections 35 & 36, Township 35 South, Range 2 West, and Sections 1 and 2, Township 36 South, Range 2 West.

#### Found

- Original BT to the Northwest,
- Stump to Northeast,
- Stump hole to Southeast and
- Stump to Southwest;

From which evidence set a temporary monument to be replaced by Army Engineers.

The original BT a 24" black oak plainly scribed bears N.66°W, 34.6 feet:

- A 5" black oak scribed CS-BT bears West 6.4 feet;
- A 40" fir scribed CS-BT (on one blaze) bears N.28¾°E. 38.8 feet;
- A 12" laurel scribed CS-BT bears S.12°E. 27.8 feet.

April 21, 1942  
C. Z. Boyden  
W.R. Young

#### NOTE:

This corner now marked by a 6" x 6" x ? concrete monument with 3½" bronze disc marked: "Boundary Monument".

June 4, 1945  
C. Z. Boyden

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

### GCDB 600100

Section corner common to Sections 1 and 2, Township 36 South, Range 2 West and Sections 35 and 36, Township 35 South, Range 2 West, W.M.

Found projecting 3 ins., the 6x6x? ins. concrete monument with center punched, 3½ ins. diam. standard U.S. Engineer Dept. brass cap, reported on 1945 addendum to first re-establishment (T36S) dated 1942.

An original bearing tree recorded by Ives and Hyde in 1854 and reported in 1942,

- A black oak, now 30 ins. diam. with axed into and partly rehealed upper blaze, brs. Record (1942): N66°W, 34.6 feet to center of tree.

Bearing trees marked in 1942 found:

- The root hole of a down fir, now 40 ins. diam., containing scribe marks, brs. Record: N28¾°E, 38.8 feet.
- The stump remains of a down Madrone, 12 ins. diam. scribed "CS" "BT", brs. Record: S12°E, 27.8 feet.
- Black Oak, 10 ins. diam., with healed blazes, brs. Record: West, 6.4 feet to center of tree at lower blaze.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Madrone, 6 ins. diam., brs. N31½°E, 22.83 feet.
- White Oak, 10 ins. diam., brs. S24°E, 20.25 feet.

Corner lies on (60%) East slope about 35 feet East of the top of slope.

December 8, 1988  
R. Frost, Tech.  
H. Durkee, Tech.

Edward McGinty  
County Surveyor

V = 17½°  
P.-393