

FIRST RE-ESTABLISHMENT

GCDB 600300

Corner to Sections 23, 24, 25 and 26, Township 35 South, Range 2 West, W.M.

Found a 2" iron pipe 6" below the surface of the ground for corner, together with a white oak BT to northwest damaged by fire, also stump holes and roots corresponding to the other record BTs.

From the said 2" pipe for corner:

- A 34" black oak scribed C.S.-BT bears N.17¼°W., 99.5 feet.
- Scribed a 7" black oak C.S.-BT which bears N.36½°E., 105.6 feet.
- Scribed an 8" black oak C.S.-BT which bears S.62¼°E., 59.2 feet.
- Scribed a 12" white oak C.S.-BT which bears S.66½°W., 47.2 feet.

September 18, 1944
C. Z. Boyden
L. J. Shorey

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600300

Section corner common to Sections 23, 24, 25 and 26, Township 35 South, Range 2 West, W.M.

Found 6 ins. deep, the 2 ins. diam. iron pipe reported found on first re-establishment, page 11, in 1944. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T35S R2W	
23	24

26	25
C.S.	
1987	

Bearing trees marked on said first re-establishment found with double healed blazes and measured to center of tree at lower blaze:

- Black Oak, now 15 ins. diam., bears Record: N36½°E, 105.8 feet. Record distance; 105.6 feet.
- White Oak, now 13 ins. diam., brs. S61½°E, 59.4 feet. Record: S62¼°E, 59.2 feet.
- White Oak, now 18 ins. diam., brs. S67¼°W, 47.7 feet. Record: S66½°W, 47.2 feet.
- Black Oak, now 40 ins. diam., brs. Record: N17¼°W, 100.6 feet. Record distance; 99.5 feet.

Corner lies 1.5 feet South of the middle of an East-West dirt road and 18 feet North of Anchor post to fences bearing East, West and South.

July 30, 1987
D. Edwards, Tech II
T. Newcomb, Tech I

Edward McGinty
County Surveyor

V = 18½°
P.-265