

FIRST RE-ESTABLISHMENT

DLC37SE

GCDB 837100

Southeast Corner of DLC No. 37, Township 35 South, Range 2 West.

Found original black oak bearing tree to the Northwest intact with scribe visible, also stump hole of white oak tree corresponding to original bearing tree to Northwest,

From which evidence set a 1½" x 36" galvanized iron pipe 24" in the ground for corner,

From which:

- A 14" White Oak scribed CS-BT bears North 25° 30' West, 109.3 feet.
- Scribed a 14" White Oak CS-BT (6 feet above ground) which bears South 88° 15' West, 130.1 feet.

August 20, 1930
C. Z. Boyden, Deputy County Surveyor
L. Pettegrew
D. King

NOTE: Corner searched for and not found on July 22, 1986. See corner card.