

**GCDB 100140**

Quarter corner common to Section 36, Township 36 South, Range 1 West, and Section 31, Township 36 South, Range 1 East, W.M.

Found both BTs destroyed. Scribe visible in stump of BT to SE.

Set 1" x 36" galvanized pipe for corner from which:

- Scribe a 16" White Oak C.S.-BT, which bears  $S83^{\circ}05'W$ , 110.9 feet.
- Scribe a 12" White Oak C.S.-BT which bears  $N88^{\circ}05'E$ , 64.0 feet.

Center line of high tension line bears West 17.2 feet.

June 29, 1928  
Boyden, Deputy County Surveyor  
O. Tice, Chainman

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 100140

Quarter corner common to Section 36, Township 36 South, Range 1 West and Section 31, Township 36 South, Range 1 East, W.M.

Found 1 ins. pipe flush with surface in ring of stone. Inserted 2½ ins. brass disk in top marked:

T36S  
R1W R1E  
36 | 31  
CS 1983

From which:

- C.S. 1928 bearing trees: (measured to center)
- Oak, 14 ins. diam., with healed over blazes, brs. N88°E, 64.60 feet. Record; 64.0 feet to face.
- White Oak, 18 ins. diam., with partial scribe visible, brs. S83°05'W, 111.3 feet. Record; 110.9 feet to face.

New references:

- White Oak, 5 ins. diam., scribed "CS" "BT", brs. N1½°E, 36.67 feet to center.
- Found ⅝" iron pin (3 feet of a fence corner) brs. South 58.20 feet.

Corner lies on Northwest slope and 3 feet East of a North-South fence line.

October 24, 1983  
E. McGinty  
R. Frost

Edward McGinty  
County Surveyor

V = 19½°  
P. -140