

FIRST RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to Sections 31 and 32, Township 36 South, Range 1 East, W.M. V = 19½°

Found 5/8 ins. diam., smooth iron pin in a mound of stone. Reference: R.S. No. 4611, recorded September 28, 1971.

Original BTs recorded by Ives and Hyde in 1854 found as follows:

- The stump depression of a downed and rotted Oak, about 15 ins. diam., bears record, N81°E, 88.44 feet.
- A Black Oak, 14 ins. diam., with healed blazes and nail driven in middle of upper blaze, bears record, S55°E, 169.62 feet to estimated face of blaze.

Over said found pin, I drove a 1 x 36 ins. G.I. pipe 32 ins. in the ground with a 2½ ins. bronze disc marked:

T36S R1E
¼S
31 | 32
Jackson County 1974

From which:

- A found 1¼ ins. diam., black iron pipe, projecting 3 ins., bears N68°E, 3.20 feet.

I marked the following trees C.S. BT and take measurements to center of trees at lower blaze:

- The most Southerly branch, 10 ins. diam. of a triple White Oak, bears N3°W, 115.15 feet.
- A White Oak, 6 ins. diam., bears N67°E, 66.0 feet.

Corner is located about 126 feet East of the center of irrigation canal and 6 feet West of the corner of East-West and South fence line.

March 19, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor