

FIRST RE-ESTABLISHMENT

GCDB 260340

Center East Sixteenth corner located in Section 20, Township 36 South, Range 1 East, W.M.

Found a small mound of stone. In the center of found mound, set a 1 x 36 ins. galvanized iron pipe, 30 ins. in the ground with a 2½ ins. brass cap marked:

T36S R1E
CE 1/16 20

C.S.
1994

Original bearing trees recorded by Howard and Rhodes in 1913 for Alex Martin tract in field book, "J" page 30, found:

- Rotted Pine stump with burned face and scribe mk. "X" brs. Record: S45½°E, 28.30 feet to estimated face.
- Rotted Oak stump remains brs. N41°E, 24.00 feet to estimated face. Record; N41°05'E.

Marked new trees "C.S." "BT" and take measurements to the center of tree at lower blaze:

- White Oak, 7 ins. diam., brs. N58°E, 34.40 feet.
- White Oak, 7 ins. diam., brs. N30½°W, 26.35 feet.

Corner lies on gentle west slope, light draw course NW, 26 feet north of corner. Old down Cedar fence posts 7 feet west of corner.

March 10, 1994
T. Newcomb, Tech.
J. Hawkinson, Tech.

Verlyn Thomas
County Surveyor

V = 17°
P.-39