

FIRST RE-ESTABLISHMENT

GCDB 300400

Section corner common to Sections 16, 17, 20 and 21, Township 36 South, Range 1 East, W.M.
 $V = 20\frac{1}{4}^\circ$

From the following evidence and at the location described below, I set a 1 x 36 ins. G.I. pipe 31 ins. in the ground with a 2½ ins. bronze disc marked:

T36S R1E
S17 S16
—————
S20 S21
Jackson County
1974

Original BTs marked by Ives and Hyde in 1854 found as follows:

- The hollow West fork of a double Black Oak, containing reverse impression of scribed "T36S R1 16" in exposed upper face, bears N18°E, 52.74 feet to scribed face. Record, N18°E, 52.14 feet.
- A stump depression in evidence at record location of original S.E. BT, S68°E, 43.56 feet.
- A Black Oak, 27 ins. diam., containing reverse scribe marks (visible inside of tree) bears S32½°W, 86.8 feet to scribed face. Record, S32°W, 85.8 feet (**Note:** This tree, badly rotted, is located on an angle point of Northerly-Southerly fence line.

I mound stones around corner, marked the following trees C.S. BT and take measurements to center of trees at lower blaze:

- A forked White Oak, 4 ins. diam., bears N68½°E, 30.8 feet.
- A White Oak, 5 ins. diam., bears S7°W, 22.9 feet.
- A forked White Oak, 6 ins. diam., bears N85½°W, 72.2 feet.
- A White Oak, 5 ins. diam., bears N4°W, 21.7 feet.

Corner lies 46.5 feet East of North-South fence line and 20 feet West of brow of hill.

March 5, 1974
E. Graham
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor