


**FIRST RE-ESTABLISHMENT**

**GCDB 300500**

Section corner common to Sections 8,9,16 and 17, Township 36 South, Range 1 East.

Set 1"x36" galvanized iron pipe, 22" in the ground with 2½" bronze cap stamped:

T.36S. R1E.



From which:

- The original bearing tree (now a 20" badly decayed pine stump) bears S62°E, 27.0 feet to the center of the stump;
- The original bearing tree (now a 24" White Oak with both blazes left intact) bears N15°E, 120.3 feet to the center of the tree;
- The original bearing tree, (now an 18" White Oak with both blazes left intact) bears N80½°W, 109.9 feet to the center of the tree. (Record= N79°W, 111.4 feet to the center)
- The original bearing tree, (now a 16" White Oak, plainly scribed), bears S24°W, 68.0 feet to the face of the upper blaze.
- A 14" White Oak, scribed "CS-BT" bears S69°E, 31.4 feet to the face of the lower blaze.
- A 6" White Oak, scribed "CS-BT" bears S35½°W, 85.3 feet to the face of the lower blaze.

February 11, 1969  
F. Roberts, Deputy County Surveyor  
Gary Kaiser