

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 4 AND 3 ONLY
GCDB 400700**

Standard corner Sections 3 and 4, Township 36 South, Range 1 East on the South boundary of Section 33, Township 35 South, Range 1 East, W.M.

Found old ¾" tube with arm on top in mound of stone for corner.

Replaced said tube with a 1" x 36" galvanized iron pipe with 2½" bronze cap stamped:

T35S 36S,R1E
 33
Sec | cor.
 4 | 3
 C.S.
 1963

From which:

- The original bearing tree (now a 28" Black Oak with scribe marks plain) bears S65½°W, 54.1 feet;
- The original bearing tree (now an 18" White Oak with old face) bears N24¼°E, 458.0 feet (Record = North 24 East, 456.72 feet);
- The original bearing tree (now a 42" White Oak snag with old face) bears S57¼°E, 449.6 feet. (Record = S57½°E, 445.50 feet);

From said pipe corner, I establish the following new witness trees:

- Scribed a 16" White Oak "CS-BT" which bears N42½°W, 125.0 feet to the face of the upper blaze;
- Scribed a 10" Yellow Pine "CS-BT" which bears N87°W, 60.0 feet to the face of the lower blaze;
- Scribed an 8" White Oak "CS-BT" which bears S25½°W, 60.8 feet to the face of the lower blaze.

November 15, 1963
F. Roberts
Lloyd Hart

Approved by:
Mark E. Boyden
County Surveyor