

FIRST RE-ESTABLISHMENT

GCDB 600340

Quarter Section Corner 23-24, Township 36 South, Range 1 East, W.M.

Found original BT to N.W., a 5" Ash, plainly scribed BT.

No evidence of original BT to S.E.

A Yellow Pine stump, 82.5 feet South, checks the official government record to a yellow pine line tree.

From which evidence:

Set a 1"x36" galvanized iron pipe for corner, From which:

- A 6" White Oak scribed C.S.-BT bears N59½°E, 27.1 feet.
- A 4" White Oak scribed C.S.-BT bears S59½°W, 9.5 feet.

October 13, 1936
C. Z. Boyden, Deputy County Surveyor
D. J. Clifford, Chainman
C. I. Bourne, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600340

Quarter corner common to Sections 23 and 24, Township 36 South, Range 1 East, W.M.

At the corner, found projecting 5 ins. in mound of stones, the 1 ins. diam. iron pipe set on first re-establishment, in 1936. In the top of said pipe in cement, set a 2½ ins. diam. brass cap marked:

T36S R1E
¼
23 | 24
C.S.
1983

Bearing trees marked in 1936 found and measured to center of trees at lower blaze:

- White Oak, 9 ins. diam., with healed blazes, brs. N59½°E, 27.05 feet. Record; 27.1 feet.
- White Oak, 5 ins. diam., with rotted out faces, brs, S58½°W, 10.15 feet. Record; S59¼°W, 9.5 feet.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- White Oak, 14 ins. diam., brs. S73°40'E, 60.60 feet.
- White Oak, 5 ins. diam., brs. S52°12'W, 11.80 feet.

Corner lies about 45 feet West of dry branch c. Southeast. Same branch brs. North approximately 30 feet.

April 13, 1983
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°
P. - 34