

FIRST RE-ESTABLISHMENT

DLC38NE

GCDB 837010

NE corner D.L.C. #38, Township 36 South, Range 1 East, W.M.

Found original BTs to Southwest and Southeast; also stump hole to Northeast, from which:

Set 3" x 8" x 18" stone for corner, from which:

- An 8" white oak scribed C.S.-BT bears N. 04° E., 38.2 feet.
- The east-southeast corner of D.L.C. #39 bears West 328.0 feet.

October 14, 1927
Boyden, Deputy County Surveyor
Kent, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC38NE

GCDB 837010

Northeast corner Donation Land Claim No. 38, Township 36 South, Range 1 East, W.M. $V = 19^\circ$

Found in mound of stone, the stone (3 x 8 x 18 ins.) set by C. Z. Boyden on First re-establishment in 1927.

Reference: Re-establishment Govt. corner, T36S R1E, Page 3.

I replaced said stone with a 1 x 36 ins. G.I. pipe set 30 ins. in the ground with a 2½ ins. bronze disc marked:

T36S R1E
N.E. Cor.
DLC 38
Jackson County 1974

The stump depression and base of a down and rotted Black Oak, about 11 ins. diam., bears

- 43.56 feet, indicating it is the original S.E. BT marked by S Truax in 1855.
- A White Oak, 12 ins. diam., with healed blazes, marked by C. Z. Boyden in 1927, bears record, $N4^\circ E$, 38.2 feet to estimated face of upper blaze.

I replaced original stone alongside corner as a memorial, marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- A White Oak, 12 ins. diam., bears $S39\frac{1}{2}^\circ E$, 10.57 feet.
- A W. Ok, 4 ins. diam., bears $N76^\circ W$, 37.9 feet.

March 13, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor