

FIRST RE-ESTABLISHMENT

DLC38SE

GCDB 177440

Southeast corner of Donation Land Claim No. 38, Township 36 South, Range 1 East, W.M.
V = 21½°

From the following evidence and at the location described below, I set a 1 x 36 ins. G.I. pipe 26 ins. in the ground with a 2½ ins. bronze disc marked:

T36S R1E
S.E. Cor.
DLC 38
Jackson County 1974

Original BTs marked by S. Truax in 1855 found as follows:

- The stump hole of a down and rotted White Oak, approximately 8 ins. diam., containing reverse impression of scribed "T36S R1 C8" bears record, N56°E, 31.68 feet.
- A White Oak snag, 10 ins. diam., containing evidence of old axe work bears, record N18°W, 22.44 feet to estimated face of blaze.

I mound stones around corner, marked the following trees C.S. BT and take measurements to center of trees at lower blaze:

- A White Oak, 9 ins. diam., bears S35½°E, 29.13 feet.
- A White Oak, 6 ins. diam., bears N74°W, 62.55 feet.
- A Black Oak, 5 ins. diam., bears N3°W, 6.0 feet.

The ¼ Cor. of Sections 18 and 17, bears East 141.0 feet. Record, 148.5 feet.

Corner is located 17 feet South of a dry branch, C. S68 E.

March 13, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor