

FIRST RE-ESTABLISHMENT

GCDB 100200

Corner Sections 25 & 36, Township 36 South, Range 2 East and Sections 30 & 31, Township 36 South, Range 3 East.

Found the original 15" x 10" x 10" corner monument, a stone marked with 1 notch on the S and 5 notches on North edges.

- Found the original NE, SE and SW witness trees.

At the exact location of ground with a bronze cap stamped:

T36S R2&3E	
Section	
25	30
<hr/>	
36	31
Cor.	
1960	

For corner, from which:

- The original witness tree (now a 24" Black Oak plainly scribed) bears N54°E 178.6 feet;
- The original witness tree (now a 30" B oak with old scar) bears S39°E, 160.4 feet;
- The original witness tree (now a 30" B oak with old scar) bears S27½°W, 101.4 feet;

I take new trees as follows:

- A 12" Ash scribed CS-BT bears N36°W, 17.6 feet;
- A 10" W oak scribed CS-BT bears S82°W, 9.7 feet;
- An 18" W oak, scribed CS-BT bears S27½°E, 23.6 feet;
- A 14" B oak scribed CS-BT bears N68½°E, 66.8 feet;

Var. 20° E
August 22, 1960
L. D. Pinkham
C. L. Birk

M. E. Boyden
Deputy County Surveyor

SEE NEXT PAGE FOR ADDENDUM TO FIRST RE-ESTABLISHMENT

**ADDENDUM TO FIRST RE-ESTABLISHMENT
GCDB 100200**

Found, exposed 6 ins., the monument and stone recorded on 1st Re-establishment.

Re-built mound of stones.

All 4 bearing trees marked on said 1st Re-establishment found in good condition with healed double blazes, however no trace of original B. Oak bearing trees was found.

Corner lies approx. 1200 ft. north of Hwy. 140 on 40% slope.

September 1, 2009

H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 200