

FIRST RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 and 8, Township 36 South, Range 3 East, W.M.

Found at the corner position, lying in a hole depression with a "¼" chiseled on side, a 13 x 11 x 5 ins. stone.

Set at this position, 25 ins. deep and in a mound of stones, a 1 x 30 ins. flanged galvanized iron pipe with a 2½ ins. diam. brass cap, marked:

JACKSON COUNTY SURVEYOR
T36S R3E
¼
S7 • S8
2004

No evidence remaining of original bearing trees.

Mark new bearing trees "CS" "BT" and take measurements to center of tree at lower blaze:

- White Fir 5 ins. diam. bears N75°E, 10.1 feet.
- White Fir 17 ins. diam. bears S25½°W, 60.03 feet.
- No other trees within reasonable limits.

Corner lies on westerly slope, approximately 30 feet east of 3-strand barbed wire fence. C.-North-South.

August 2, 2004

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 67

V. - 18°