

FIRST RE-ESTABLISHMENT

GCDB 340200

Quarter corner common to Sections 28 and 33, Township 36 South, Range 3 East, W.M. $V = 19\frac{1}{2}^\circ$

Found basalt stone, 14 x 12 x 10 ins. firmly set and marked as described by R. Moore in 1883, with "¼" on N. face.

I replace said stone with a 1 in x 36 ins. G.I. pipe set 30 ins. in the ground with a 2½ ins. bronze disc marked:

T36S R3E
28
¼S —
33
C.S.
1973

- The stump depression, with Fir fragments, of an original BT bears record, $N41^\circ E$, 31.68 feet.
- The stump depression of original S.W. BT bears record, $S14^\circ W$, 19.14 feet.

I mound stone around corner, marked the following trees C.S. BT, and take measurements to center of trees at lower blaze:

- A Douglas Fir, 16 ins. diam., bears $S39^\circ W$, 9.80 feet.
- A Douglas Fir, 13 ins. diam., bears $N56^\circ W$, 10.0 feet.

Original stone deposited alongside as memorial to corner.

September 13, 1973
E. Graham
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
GCDB 340200**

Quarter corner common to Sections 28 and 33, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 5 ins. with the original stone alongside, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st Re-establishment in 1973, marked:

T36S R3E
28
¼S—
33
C.S.
1973

Bearing trees recorded on said first Re-establishment, found with healed double blazes and measured to center at lower blaze:

- D. Fir, now 26 ins. diam. brs. record; S39°W, 9.8 ft.
- D. Fir, now 22 ins. diam. brs. record; N56°W, 10.0 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. Fir 15 ins. diam. brs. N55¾°E, 32.0 ft.

Corner lies approx. N30°E, 300 ft. from "Y" intersection of spur roads.

August 14, 2012
H. Durkee

Scott Fein
Deputy Jackson County Surveyor

P. – 27
V. – 15°20'