

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 4 ONLY
GCDB 340700**

North quarter corner of Section 4, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 12 ins. in a mound of stones with an aluminum fence post and "Attention" sign 2 ft. east, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1977, marked:

T36S R3E
¼ ———
S4
1977

Bearing tree recorded by the BLM in 1977

- A cedar, now 14 ins. diam. with a healed single blaze, brs. record; S20°W, 13.2 ft. to center at base.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 6 ins. diam. brs. S33°E, 15.4 ft.

Corner lies approx. 700 ft. S75°W from bend in old logging spur road.

January 25, 2012
H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 122
V. – 13°35'