

## FIRST RE-ESTABLISHMENT

GCDB 400240

Quarter corner common to Sections 27 and 28, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 10 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E  
¼  
S28 | S27  
1962

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center at base:

- Fir, now 22 ins. diam., brs. S82¼°E, 26.4 ft. Record; S81°E.
- Sawed Fir stump 24 ins. diam., brs. record; S45°W, 48.2 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 13 ins. diam., brs. N11½°E, 11.1 ft.
- Southeasterly fork of a Cedar, 9 ins. diam., brs. N48¾°W, 43.8 ft.
- W. Fir 13 ins. diam., brs. S1½°W, 8.9 ft.

Corner lies approx. 300 ft. easterly of a 4-wheel-drive spur road.

August 15, 2012  
H. Durkee

Scott Fein  
Deputy Jackson County Surveyor

P. – 28  
V. – 14°45'