

FIRST RE-ESTABLISHMENT

GCDB 400540

Quarter corner common to Sections 9 and 10 of Township 36 South, Range 3 East, W.M.

Found at corner position exposed 6 ins. the 2½ ins. diam. galvanized iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962 and marked:

T36S R3E
¼
S9 | S10
1962

Original bearing trees recorded by R. Moore of the GLO in 1883 found with healed blazes and measured to center at base:

- Fir snag bears S 81° E, 8.6 feet. Record: S 83° E.
- Cedar now 22 ins. diam. bears Record: N 49° W, 7.9 feet.

Bearing trees recorded by the BLM in 1962 found with healed single blazes and measured to center at base:

- White Fir, now 14 ins. diam. and dying, bears S 48° E, 13.2 feet. Record: S 46° E.
- White Fir, dead and down bears S 34° W, 13.9 feet. Record: S 37° W.

Marked new bearing trees "CS" "BT" and took measurements to center at lower blaze:

- Ponderosa Pine 8 ins. diam. bears S 22½° W, 19.5 ft
- Douglas Fir 6 ins. diam. bears S 28° E, 52.0 feet.

Aluminum post with sign 3 feet west of corner. Corner lies approximately 100 feet east of gravel road.

April 24, 2007

B. Beeman
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P - 104
V - 13°35'